

If safe, they will be taken in to the Electrical Systems Manager for replacement.

Purpose

To ensure the safe handling of energized parts with hand tools.

Procedure

When an energized part, the tool must be inspected by the user for damage that the tool is in operating condition.

Defective tools are to be taken immediately to the Electrical Manager and tagged "Out of Service" with a red tag.