

a) **Smoke** is made to pass **to** the device. If face is **hot** the device should be replaced.

3) **Check** for correct wiring with a circuit tester.

4) **Check** for correct wiring and polarity **to** the device with the multimeter.

4) **Report** any unusual **findings** to the Electrical Engineer.