

35. N. 20. To ensure moisture free air. Recommendations and specifications.

Purpose

To ensure moisture free air.

Procedure

Quarterly:

1. Clean compressor and condenser.
2. Visual and noise checks.