

Procedure

Annual:

1. Visual inspection and check for loose connections

1

2. Take and record voltage and ampere readings.

2

3. Check for overheating

Manager.